

Instrument/ Model Number	Instrument/ Software Version	iLinkPro/PAM Resource Kits	Kit/ Part No.
<b>READERS</b>			
IN Cell Analyzer 1000	Amersham INCell1000, InCell (v3.2)	Amersham INCell Adapter (v3.0), Setup.exe (v9.0.333.0)	116924
Amersham LeadSeeker Reader	Assay Vision - AIS (v6.1)	Amersham LeadSeeker, Build (v1.0.8), ICP (v1.0.36), IA (v2.0.25)	101313
ABI FMAT 8100, IA (v2.0.2)	FMAT 8100 Software (v.2.0.1)	Applied Biosystems FMAT 8100	101700
Aurora VIPR II	Aurora VIPR II Software Package	Aurora VIPR II, IA (v2.0.1)	101556
PowerWave HT-1 Reader	BioTek KC4 (v3.01, Rev 7), Build (v2.0.3)	BioTek PowerWave HT, IA (v2.0.6)	101611
Microplate Reader (Software)	Build (v2.0.4), IA (v2.0.0.4), KC4_32.exe file of KC4 (v3.4, Rev 21), and Bio-Tek Clarity Software (v4.1.1.11 if Clarity is the instrument)		114509
BMG FLUOstar (403) Galaxy Reader	FLUOstar Galaxy Software (v4.20-0)	BMG FLUOstar Reader	101473
NEPHELOstar Galaxy Plate Reader	NEPHELOstar Galaxy Software (v4.10-0)	BMG NEPHELOstar Galaxy Reader	101472
BMG Lumistar Reader, IA (v2.0.14)	BMG Lumistar Software (v3.00-0)	BMG Lumistar Reader (refer to actual hardware for version)	102046
BMG RubyStar	CD Integration Kit	CD Integration Kit-BMG RubyStar	
BMG POLARstar OPTIMA	BMG POLARstar, Build (v2.0.2), IA (v2.0.2)	BMG POLARstar OPTIMA	105820
BMG PHERAstar Firmware (v1.20)	Control Software (v1.5.0)	IA (v2.0.3)	113607
ArrayScan	Cellomics ArrayScan ICP SW (v5.0.1 or higher)	IA (v2.0.14)	109400
Vmax and SpectraMax	SoftMax PRO (v4.3.1 and v4.6)	Build (v1.0.9), ICP (v1.0.96), IA (v.2.0.319)	79276
MDC Analyst GT Reader	ActiveX Suite (v3.00.15)	ICP (v.1.0.035), IA (v2.0.010)	109750
MDC Flipr 384	Build 2.1.2 ICP (v2.0.4 ) and IA (v2.0.4)	MCC Flipr 3	101797
MDC SpectraMax 384 Plus	MDC SoftMax Pro Software (v.4.8), Firmware (v1.17)	MDC SoftMax Pro Reader, IA (v2.0.30)	112867
Packard TopCount NXT	N/A	IA (v2.0.2), ICP (v2.0.5)	100722
Perkin Elmer Packard AlphaQuest Reader	Perkin Elmer Packard AlphaQuest Control Software (v2.15)	Perkin Elmer Packard AlphaQuest Reader IA (v2.0.6)	101796
Perkin Elmer Packard TopCount NXT	Perkin Elmer Packard TopCount NXT Software (v1.06) Elmer Packard TopCount NXT Computer	Perkin Elmer Packard TopCount NXT and Network Card installed on Perkin	100722
Perkin Elmer Packard Fusion	Perkin Elmer Packard Fusion ICP (v1.0.5) & IA (v2.0.2)	Perkin Elmer Packard Fusion	100726
Wallac Victor II, III, 1420 Multilabel Counter Readers	Wallac 1420 Software (v2.00, Rev 9)	ICP (v1.0.30), IA (v2.0.37)	100718
Wallac Victor V, 1420 Multilabel Counter	Wallac 1420 Software (v2.00, Rev 9)	Wallac Victor Reader, ICP (v1.0.7) and IA DD (v1.0.3), DI (v1.0.3 and 2.0 v2.0.25)	100718
Wallac Victor V, II 1420 Multilabel Counter	Wallac 1420 Software (v2.00, Rev 9)	Wallac Victor Reader, ICP (v1.0.7) and IA DD (v1.0.3), DI (v1.0.3 and 2.0 v2.0.25)	100718

Instrument/ Model Number	Instrument/ Software Version	iLinkPro/PAM Resource Kits	Kit/ Part No.
<b>READERS (cont)</b>			
Wallac 1450 MicroBeta TriLux Reader, Build (v2.0.9), IA (v2.0.65)	MicroBeta Workstation Software (v3.10)	Wallac MicroBeta Trilux Reader	100719
Wallac ViewLux Reader	Wallac ViewLux Software (v2)	Wallac ViewLux 1430 Reader	101328
EnVision	EnVision IA (v2.0.100)	EnVision Build (v2.0.6)	104225
Tecan Genesis	Tecan Gemini Standard Software (v3.20 or 3.40)	Tecan Genesis	101152
Tecan Magellan	Tecan Magellan, Build (v.2.0.5)	Tecan SpectraFluor Plus Reader	104675
Tecan Magellan	Tecan Magellan, Build (v.2.0.5)	Tecan Safire (Fixed Wavelength) Reader	104675
Tecan Magellan	Tecan Magellan, Build (v.2.0.5)	Tecan Ultra	104675
Tecan Magellan	Tecan Magellan, Build (v.2.0.5)	Tecan Sunrise Reader	104675
Tecan Magellan	Tecan Magellan, Build (v.2.0.5)	Tecan Genios	104675
Magellan GENios	Tecan Magellan (v3.11)	IA (v2.0.12)	103052
Tecan Safire (Variable Wavelength)	Build (v.2.0.2) no ICP, IA (v2.0.39)	Tecan Safire	105512
Wellwash AC, ICP (v1.0.1) and IA (v2.0.1)	Wellwash.dll (v1.0)	Wellwash AC	101410
MultiSkan Ascent Reader, IA (v2.0.16)	LabSystems Ascent Software (v2.4.1 & v2.4.2)	LabSystems MultiSkan Ascent Reader (v1.24)	101471
MultiSkan Ascent Reader, IA (v2.0.16)	LabSystems Ascent Software (v2.4.1 & v2.4.2)	LabSystems Fluoroskan Reader (CF)	101471
MultiSkan Ascent Reader, IA (v2.0.16)	LabSystems Ascent Software (v2.4.1 & v2.4.2)	LabSystems Nepheloskan Reader	101471
MultiSkan Ascent Reader, IA (v2.0.16)	LabSystems Ascent Software (v2.4.1 & v2.4.2)	LabSystems Luminoskan Reader	101471
MultiSkan Ascent Reader, IA (v2.0.16)	LabSystems Ascent Software (v2.4.1 & v2.4.2)	LabSystems FL Reader	101471
AcumenExplorer Reader	Build 2.0.2 IA (v2.0.100)	AcumenExplorer Reader	104949
<b>LIQUID HANDLERS</b>			
AQUAmax 1536 Dispenser	AQUAmax 1536 Software (v1.2.0.2)	Embla 96-384 and AQUAmax, ICP (v1.0.10) and IA (v2.0.9)	102190
AquaMax Dispenser	N/A	ICP (v1.0.23)	111822
ASYS Flexispense	Build 2.0.1 - ICP (v1.01.01), IA (v1.01.01)	ASYS Flexispense	119730
BioTek Precision 2000, IA (v2.0.1)	PrecisionPower2.exe (v2.0.2.1), BTI AutoDispenser ActiveX (v2.0.1.2)	ICP (v.2.0.142), IA (v2.0.29) and Build (v2.0.12)	101951
BioTek uFill 96/384 Well Reagent Dispenser	ActivexX Software (v1.0.0.3)	ICP (v1.0.1772.40154), IA (v2.0.0.2)	112600
Cartesian SynQuad IA (v2.0.1)	AxSys Software (v1.79.12.0)	Cartesian SynQuad	101414
RapidPlate (v2.4)	RapidPlate RS 232	RapidPlate RS232	105390
FlexDrop	N/A	IA (v2.06), ICP (v1.1.16)	108198
FlexDrop	N/A	IA (v2.06), ICP (v1.1.16)	78659
Multidrop 384 (v2.0), ICP (v2.0.10) and IA (v2.0.19)	N/A	Titertek Multidrop 384	78997
Multidrop (v2)	ICP (v2.0.32) and IA (v2.0.35)	Build (v2.0.2)	105294
Multidrop (v2)	N/A	Baseline Build (v2.0.16), ICP (v2.0.51) & IA (v2.0.52)	105294

Instrument/ Model Number	Instrument/ Software Version	iLinkPro/PAM Resource Kits	Kit/ Part No.
<b>LIQUID HANDLERS</b> (cont)			
Zymark Multiple Reagent Dispenser	Zymark MRD ICP (v2.0)	Zymark MRD, ICP (v2.0.24) and IA (v2.0.13)	N/A
Well Mate	Build 2.0.1 ICP (v2.0.0.1), IA (v2.0.0.1)		116034
AquaMax DW4 Dispenser	Build 2.0.5, ICP (v1.0.30), IA (v2.0.19)	Build (v2.0.4), ICP (v1.0.22), IA (v2.0.16), Firmware (v7.1)	112198
<b>WASHERS</b>			
ELx405 Plate Washer		BioTek ELx405 Plate Washer (v1.0)	
BioTek ELx405 Plate Washer	BioTek 405 Instrument Control Program (v2.0) & BioTek BTI Autowasher (v1.16.8 Requires ActiveX component)	BioTek ELx405 Plate Washer (v2.11), ICP (v2.0.88) and IA (v2.0.43)	100696
BioTek ELx405 Select Plate Washer	BioTek 405 Instrument Control Program (v2.0) and BioTek BTI Autowasher (v1.16.8 Requires ActiveX component)	BioTek ELx405 Plate Washer (v2.11), ICP (v2.0.88) and IA (v2.0.43)	100696
BioTek ELx405 Magna Plate Washer	BioTek 405 Instrument Control Program (v2.0) and BioTek BTI Autowasher (v1.16.8 Requires ActiveX component)	BioTek ELx405 Plate Washer (v2.11), ICP (v2.0.88) and IA (v2.0.43)	100696
BioTek ELx405 Plate and Select Washer	BioTek 405 Instrument Control Program (v2.0) and BioTek BTI Autowasher (v1.16.8 Requires ActiveX component)	Build (v2.08), ICP (v2.0.45) and IA (v2.0.33)	100696
Embla 96/384 Washer	Skatron Firmware (v2.8), Software (v3.01)	Embla 96-384 Washer	100724
Embla Washer	N/A	ICP (v1.0.33)	111714
Tecan Power Washer 384	Tecan Win Wash Plus (v2.02)	Tecan Power Washer 384	101407
<b>BAR CODE READERS</b>			
Keyence BL-600 Barcode Reader	N/A	ICP (v1.0.10) and IA (v2.0.9)	104514
Ms-710 and M3 Barcode Readers	Build 12, ICP (v3.0.0.55) and IA (v2.0.0.88)	Microscan Scanner MS-710	79290
Symbol Barcode Reader, ICP (v1.0.8), IA (v2.0.16)	This resource Kit Supports CLARA 2001	Symbol Technologies LS 1220	102475
<b>BAR CODE LABELERS</b>			
Beckman Print and Apply, IA (v2.0.11)	Beckman Software Package	Beckman Microplate P&A Station	101553
Velocity BarCode Print and Apply Station	Vcode ActiveX (v2.1.3)	ICP (v1.0.1) and IA (v2.0.1)	101170
Vcode Print and Apply	Velocity11 Vcode3 ActiveX (v1.6)	IA (v2.0.13) and ICP (v1.0.27)	100334
<b>PLATE STORAGE</b>			
Kendro Cytomat 2 Incubator	KC 2 (v1.0) Service Software	ICP (v1.0.17) and IA (v2.0.9)	101269
Zymark Incubator, Liconic Incubator, Hereaus Cytomat 600	Zymark Incubator ICP (v2.0.78)	Zymark Incubator (v2.0), ICP (v2.0.78) and IA (v2.1.21)	79282
TekCel Plate Server, IA (v2.1.0)	TekCel Instr.Control Prog. ServerStoreRemote.exe (v1.0) Jan. 2002 or Later Compatible Versions	TekCel Plate Server/ Plate Store System	101557

Instrument/ Model Number	Instrument/ Software Version	iLinkPro/PAM Resource Kits	Kit/ Part No.
<b>SEALERS</b>			
Marsh Heat Sealer, ICP (v1.0.55) and IA (v2.0.21)	N/A	MARSH Heat Sealer (ALPS300)	101040
Velocity 11 PlateLoc, ICP (v1.0.7) and IA (v2.0.3)	Velocity 11 PlateLoc ActiveX (v3.2.0.1)	Velocity 11 PlateLoc Thermal Plate Sealer	101698
REMP Portrait Heat Sealer	REMP ActiveX Device Interface (v1.0-dated 8/13/01)	REMP ActiveX Device Interface	101412
REMP Landscape Heat Sealer	REMP ActiveX Device Interface (v1.0-dated 8/13/01)	REMP ActiveX Device Interface	101412
REMP Landscape Piercer	REMP ActiveX Device Interface (v1.0-dated 8/13/01)	REMP ActiveX Device Interface	101412
REMP CSP (384 Tube Sealer)	REMP ActiveX Device Interface (v1.0-dated 8/13/01)	REMP ActiveX Device Interface	101412
<b>PIERCERS</b>			
ABGene Piercer ASP 50	N/A	ICP (v1.0.0.23) and IA (v2.0.3)	109833
Velocity 11 PlatePierce, ICP (v1.0.4) and IA (v2.0.5)	Velocity 11 ActiveX OCX Vpierce.ocx (v2.1.0.2)	Velocity 11 PlatePierce Station	101699
<b>TRANSPORT DEVICES</b>			
Mitsubishi "E" Series Robot	N/A	ICP (v2.1.0.29) and IA (v2.0.42)	78753
<b>THERMO CYCLERS</b>			
MJ Research PTC 200	MJ Research PTC 200 DNA Engine	MJR PTC 200	101474
MJResearch TETRAD, ICP (v1.0.15 and v2.0.4)	N/A	MJResearch PCT 225 Tetrad Cyclor	102521
MJ Research PTC 200	N/A	Build (v1.0.7), ICP IA (v2.0.0.36) and (v1.0.1728.22267)	109752
9700 Thermo Cyclor Dual 384 AutoLid	ABI PCRNET Software with Java Virtual Machine	IA (v1.0.8) and ICP (v1.06)	112602
<b>CENTRIFUGES</b>			
Velocity11 Vspin	VSpinAccess2 ActiveX Control Module v.1.1.3, FW (v1.0.6), HW (v2.0.0), VSpin ActiveX (v4.2.2), and VSpin HW (v2.3)	ICP (v2.0.142), IA (v2.0.29) and Build (v2.0.12)	108908
<b>MISCELLANEOUS</b>			
COPAS	N/A	ICP (v1.0.35) and IA (v2.0.0.6)	109577
MassLynx	MassLynx, OpenLynx Manager, AutoLynx (v4.0) SPI or compatible	IA (v2.0.23) and ICP (v2.0.32)	109141
N/A	N/A	Waste Bin Adapter	
REF085 CLARA Excell Install Kit			



**Corporate Headquarters**  
68 Elm Street  
Hopkinton, MA 01748-1668

Tel: 1.508.435.9500  
Email: [cust.support@caliperLS.com](mailto:cust.support@caliperLS.com)  
[www.caliperLS.com](http://www.caliperLS.com)

©2008 Caliper Life Sciences, Inc. All rights reserved.  
Caliper, the Caliper logo, Zymark, iLinkPro and RapidPlate are tradenames and/or trademarks of Caliper Life Sciences, Inc. All other names are trademarks of their respective companies.